

Facility Name & Location:
Atlantic Relocation, Indianapolis, Indiana

Photographer:
Shelly Lam

Camera:
Canon Powershot SD750

**Dates Photographs
Were Taken:**

3/18/2015

Photo No.
IMG_8744

Time:
0900

**Direction Photo
Taken:**
S

Photo Description:
Pad-mounted
transformer owned by
Duke Energy



Photo No.
IMG_8746

Time:
0902

**Direction Photo
Taken:**
NW

Photo Description:

Above-ground storage
tank



Photographer: Shelly Lam		
Photo No. IMG_8747	Time: 0902	
Direction Photo Taken: W		
Photo Description: Vehicle fueling area. No secondary containment. Flow goes to storm drain.		

Photo No. IMG_8749		
Time: 0903	Direction Photo Taken: NE	
Photo Description: Tank loading area. No secondary containment. Flow goes to storm drain.		

Photographer: Shelly Lam	
Photo No. IMG_8750	Time: 0903
Direction Photo Taken: E	
Photo Description: Oil staining inside secondary containment	



Photo No. IMG_8751	Time: 0904
Direction Photo Taken: E	
Photo Description: Aboveground storage tank in foreground. Safety cones in background located on top of storm drain.	

